




On this ECU it is possible only the DIRECT CONNECTION



ECU VISTEON DCU 102

Only on ECU DCU 102 it can happen that there is no communication on CAN line and the ECU communicates on K line. If there is no correct communication on CAN try with K line wire connecting it on the pin J2 as described on the following picture.

**DIRECT CONNECTION**

Connect the universal wiring to POL4 & POL5 and to the connector as shown.

