





8 CILINDERS VALVETRONIC ENGINE ECU: soldering pads are located in the lower part of the ECU



DIRECT CONNECTION

Among these 14's we will use the first 10's from the left to solder the strips or guiding pin strips.
The coloured stripe of the flat cable identifies the pin number 1 and MUST face left, you should look at the ECU with the connector placed upwards(eprom side).



DIMA CONNECTION