

ECU SIEMENS HMC THETA PI


DRIVER: Bdm/Jtag mode → Bdm MPC →
MPC55x/56x

MICRO: MPC55x/56x

INFO

(EN) Connect the following pinout with the Tricore Cable.

(IT) Collegare il seguente pinout con il cavo Tricore.



(EN) Material required:

(IT) Materiale necessario:

Siemens Marelli
BDM Adapter tight



Gray flat cable



Pin strip



(EN) It needs to clean the card in the interested zone in a such way that it is deprived of any protective agent and solder the pin strip and then insert Siemens adapter respecting pin 1.

(IT) Occorre pulire la scheda nella zona interessata in modo tale che sia priva di qualsiasi agente protettivo, saldare i pin strip e successivamente inserire l'adattatore Siemens rispettando il pin 1.

