



For the correct CHECKSUM calculation in RACE EVO system with CK_81 it is necessary to start from the MPC file extracted from DIM file. Only in this way RACE EVO system won't show any error on the original file of the vehicle.

The pads are in the lower part of the ECU, as shown in the picture




IMPORTANT:

To communicate with the BDM it is necessary to link the two pads shown in **LINK 1** picture. Remove this link before connecting back ECU to the car.




WARNING: the adapter F32FL009 can be identified by the code AD02 written on the PCB sul PCB.



DIRECT CONNECTION with DELPHI2 F34FL009

Connect adapter F34FL009 as in the picture.



DIMA CONNECTION with DELPHI2 F34DM009